

# Final Reclamation Inspection

March 2, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 328998

Inspection Document #: 697502646

Weld County, CO

SESE Section 15 T2N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: CANNON W #14-33D  
Location ID: 328998



**Photo 1.** Photo taken from the western well location, facing East. Photo illustrates only one well has been drilled at the location and reclamation is in-process.

