

Inspection Photos  
Operator: Simcoe  
API: 067-08713  
Date: 3/9/2021




Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western fill slope facing northwestward. Revegetation is progressing with sand dropseed, western wheatgrass, and rubber rabbitbrush.





Photos 3. View of perimeter wattles no longer that are full of sediment and no longer functioning.



Photo 4. View of the reference area comprised of pinyon and juniper woodland, with understory of grasses and forbs such as Palmer's penstemon and Indian ricegrass.