

Inspection Photos

3/9/2021

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335573

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335573



Photo 1: 2009 COGIS aerial imagery. Photo shows overview of the Location. Pits on the south end of the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335573



Photo 2: 2013 COGIS areal image. Cuttings appear evident on the south end of the Location. Pits closed.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335573



Photo 3: 2017 COGIS areal image. New pits with cuttings become evident on the southeastern are of the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335573



Photo 4: 2019 COGIS areal image. Pits with cuttings remaining on southeast end of the Location. Little appears to have changed since 2017.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335573



Photo 5: Photo taken from the eastern areas of the Location, facing south. Photo shows pits with cuttings remain open on the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335573



Photo 6: Photo taken from the eastern areas of the Location, facing southwest. Photo shows pits with cuttings remain open on the Location.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335573



Photo 7: Photo of pit with cuttings on the southeast end of the Location, facing south.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location ID: 335573



Photo 8: Photo of pit with cuttings on the southeast end of the Location, facing west.

