

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/11/2021

Submitted Date:

03/12/2021

Document Number:

701002575**FIELD INSPECTION FORM**Loc ID 321751 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**OGCC Operator Number: 61250Name of Operator: MULL DRILLING COMPANY INCAddress: 1700 N WATERFRONT PKWY B#1200City: WICHITA State: KS Zip: 67206-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Akers, Tracy	719-342-1813	takers@mulldrilling.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207917	WELL	PR	12/09/2020	GW	017-06852	NW ARAPAHOE UNIT 32	PR

**General Comment:**[Routine Inspection](#)

## Location

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal signs by tanks		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 5		
Comment:	Electric panel, cathodic rectifier, chemical tank w/containment, elec circ pump by oil tanks, telemetry equipment		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator in metal shed on west side of vent tank		
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:	Treater on west side of HHT with metal shed		
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		

Comment: <a href="#">Treater on west side of water tank</a>		Date:
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment: <a href="#">Sentry 320</a>		Date:
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment: <a href="#">Electric motor</a>		Date:
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		38.857350,-102.153210
Comment: <a href="#">Fiberglass open top water tank. Water tank is on east side of HHT</a>					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: <a href="#">Shared berms with treaters</a>					
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		38.857600,-102.153220
Comment: <a href="#">Vent tank on northeast corner of location</a>					
Corrective Action:					
Date:					

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		38.857310,-102.153580
Comment: <a href="#">3-Production tanks on west side of location</a>					

Corrective Action:		Date:	
<b>Paint</b>			
Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			
<b>Berms</b>			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Earth	Adequate	Walls Sufficient	Base Sufficient
Comment:			
Corrective Action:	Date:		
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:	Date:		
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:	Date:		

Inspected Facilities									
Facility ID:	207917	Type:	WELL	API Number:	017-06852	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Central tank battery for (NWAU 29, 30, 31, 32, 34, 35)								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701002585	location photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5375129">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5375129</a>