

**TEP ROCKY MOUNTAIN LLC**  
**PA-66S95W 34NESW**  
**Location # 335299**



**Weathering sign. Battery sign is not at tank battery.**



**Capacity volumes on tank labels are unreadable from a distance.**



**TEP ROCKY MOUNTAIN LLC**  
**PA-66S95W 34NESW**  
**Location # 335299**





**TEP ROCKY MOUNTAIN LLC**  
**PA-66S95W 34NESW**  
**Location # 335299**



**Well signs are cracking and peeling.**



**Well signs are cracking and peeling.**



**TEP ROCKY MOUNTAIN LLC**  
**PA-66S95W 34NESW**  
**Location # 335299**



**Well signs are cracking and peeling.**



**Well signs are cracking and peeling.**

**TEP ROCKY MOUNTAIN LLC**  
**PA-66S95W 34NESW**  
**Location # 335299**



**Unmarked deadman.**



**Unmarked deadman.**



**TEP ROCKY MOUNTAIN LLC**  
**PA-66S95W 34NESW**  
**Location # 335299**



**Debris on location.**



**Debris on location.**





**TEP ROCKY MOUNTAIN LLC**  
**PA-66S95W 34NESW**  
**Location # 335299**



**Debris on location.**



**Debris on location.**

**TEP ROCKY MOUNTAIN LLC**  
**PA-66S95W 34NESW**  
**Location # 335299**



**Drain needs maintained.**



**Drain needs maintained.**



**TEP ROCKY MOUNTAIN LLC**  
**PA-66S95W 34NESW**  
**Location # 335299**



**Ditch on road needs maintained.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**TEP ROCKY MOUNTAIN LLC**  
**PA-66S95W 34NESW**  
**Location # 335299**



**Sediment disturbing drainage bmp.**