

Inspection Photos

Loc#324148

Operator: Terra

Insp#: 692403182

Insp Date: 3/5/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View into Location.

March 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos: Terra Langstaff Loc#324148



Photo#2:
View over pad to Southeast.



Photo#3:
Rutting at entry to location..

March 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos: Terra Langstaff Loc#324148