

# *Inspection Photos*

*Loc#311663*

*Operator: Terra*

*Insp#: 692403187*

*Insp Date: 3/5/21*





Photo#1:  
Overview of Location.

March 5, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Insp Photos:Terra Federal Loc#311663



Photo#2:  
Rutting, degradation of site.

March 5, 2021



Photo#3:  
Rutting, degradation of site



Photo#2:  
Stream crossing needs maintenance/stabilization.



Photo#3:  
Stream crossing needs maintenance/stabilization,  
view to East with flow.

March 5, 2021