

Inspection Photos

Loc#335637

Operator: Terra

Insp#: 692403188

Insp Date: 3/5/21





Photo#1:
Overview of Location.

March 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos:Terra DOE Loc#335637



Photo#2:
Rutting, degradation of site.



Photo#3:
Cellar of Well API#045-06486

March 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos:Terra DOE Loc#335637



Photo#3:
Rutting, degradation of site.



Photo#4:
Rutting, degradation of site.

March 5, 2021



Photo#6:
Interim Area.

March 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos:Terra DOE Loc#335637