

Inspection Photos

Loc#322441

Operator: Terra

Insp#:692403192

Insp Date: 3/5/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

March 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos: Terra Clough Loc#322441



Photo#2:
Interim area.



Photo#3:
Pad & access road require stabilization.

March 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos: Terra Clough Loc#322441