

Inspection Photos
Location Name: JT Morris A #1 Well Tie
Spill/Release Point ID: 479418



Spill/Release Point ID #479418 location photo.



Spill/Release Point ID #479418 point source has been repaired and backfilled.

Inspection Photos
Location Name: JT Morris A #1 Well Tie
Spill/Release Point ID: 479418



Valve can uphill and to the west of Spill/Release Point.



Location of Spill/Release Point ID #479418 has been scraped.