

Inspection Photos

Loc#418061

Operator: Grizzly

Insp#: 692403217

Insp Date: 3/11/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location and insert of interim vegetation.

March 11, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Federal Loc#418061



Photo#2:
Interim area.



Photo#3:
Interim area.

March 11, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Federal Loc#418061