

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2021

Submitted Date:

03/10/2021

Document Number:

701002525**FIELD INSPECTION FORM**Loc ID 303350 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 25255Name of Operator: DUKE GAS COMPANY LLCAddress: 22500 COUNTY RD 24City: VERNON State: CO Zip: 80755**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Cantrall, Diana		djcantrall@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252951	WELL	PR	06/01/2017	GW	125-06828	CANTRALL 2-35	DM

General Comment:[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Lease sign for Cantrall 2-35 by meter shed		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Metal panels around wellhead and gas scrubber		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 4		
Comment:	3-Vertical gas separators 50% buried by meter shed for the Cantrall 35-1, 35-7, 35-8 1-Vertical gas separator 50% buried by meter shed abandoned and not in use (for Cantrall 2-35)		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:	Shared meter run for (Cantrall 35-1, 35-7, 35-8) 240' north of wellhead		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Gas scrubber at wellhead (for domestic use). Telemetry equipment at meter shed		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 252951 Type: WELL API Number: 125-06828 Status: PR Insp. Status: DM**Producing Well**

Comment: Well is converted to domestic well for farmhouse and producing. Meter run is removed at meter shed and VGS is still in place at meter shed. Central meter run for (Cantrall 35-1, 35-7, 35-8) 240' N of wellhead

Corrective Action: Submit Sundry notice for current well status (DM)

Date: 04/08/2021

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402624056	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5372383
701002550	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5372375