

# Inspection Photos

3/16/2021

Operator: CHEVRON USA INC - 16700

Location ID: 382974

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 382974



**Photo 1:** Photo taken from the Location. Photo shows example of wattles on the Location; it was observed that wattles have not been installed in accordance with good engineering practices (trenched and backfilled).





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 382974



**Photo 2:** Photo taken from the southern area of the Location where channelized erosion has been documented. Photo shows Operator has placed rock aggregate, as well as rock socks within the area of erosion. Photo also shows wattle BMPs on the Location remain improperly installed.





Inspection Photos  
Operator Name: CHEVRON USA INC - 16700  
Location ID: 382974



**Photo 3:** Continued from photo 2. Photo shows wattles on the Location have not been installed in accordance with good engineering practices (trenched and backfilled).

