

Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT-68S96W /17SESW

Location ID: 334066



Photo #3153 from entrance to location.



Photo #3155 Flow line heating insulation open ended and not capped.