

# *Inspection Photos*

*Loc#419675*

*Operator: Terra*

*Insp#: 692403219*

*Insp Date: 3/11/21*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location and fill slope.



March 11, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Insp Photos: Terra Jolley Loc#419675



Photo#2:  
Cut slope, view Northeast.



Photo#3:  
Cut slope, view Southwest.

March 11, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Insp Photos: Terra Jolley Loc#419675



**Photo#2:**  
Erosion, sediment migration on Cut.



**Photo#3:**  
Erosion, sediment migration on Cut.

March 11, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Insp Photos: Terra Jolley Loc#419675



Photo#2:  
Access road entry.

March 11, 2021



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#3:  
Working Pad surface.

Insp Photos: Terra Jolley Loc#419675