

Final Reclamation Inspection

March 10, 2021

Operator: NOBLE ENERGY INC - #100322

Location ID: 461262

Inspection Document #: 697502670

Weld County, CO

NENE Section 10 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Roskop NE Tank battery
Location ID: 461262



Photo 1. Aerial imagery from 2019. Photo illustrates the former Roskop NE Tank battery (red circle). The corner of this property is flood irrigated and outside of the pivot circle.





Photo 2. Photo taken east of the tank battery location, facing West. Photo illustrates all equipment has been removed from the tank battery. However, it does not appear the tank battery was properly contoured to the surrounding area and does not have any establishment of alfalfa. If the location is not properly contoured, then flood irrigation is likely compromised and not successfully being irrigated.

Inspection Photos
Location Name: Roskop NE Tank battery
Location ID: 461262



Photo 3. Photo taken from the western tank battery location, facing Southeast. Photo illustrates the main vegetation is common oat and Kochia, which is not reflective of reference crop areas.



Inspection Photos

Location Name: Roskop NE Tank battery

Location ID: 461262



Photo 4. Close up photo of common oat established within the tank battery location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502670

Inspection Photos
Location Name: Roskop NE Tank battery
Location ID: 461262



Photo 5. Close up photo of Kochia established within the tank battery location.



Inspection Photos
Location Name: Roskop NE Tank battery
Location ID: 461262



Photo 6. Close up photo of reference crop vegetation (alfalfa).



Inspection Photos
Location Name: Roskop NE Tank battery
Location ID: 461262



Photo 7. Reference crop vegetation.

