

Inspection Photos
Location Name: DF Ranch 15-42
Location ID: 410055



Photo 1 – Wellhead

Photo 2 – Pumping Unit

Inspection Photos
Location Name: DF Ranch 15-42
Location ID: 410055



Photo 3 – Unmarked 1” Riser at Wellhead