

# Inspection Photos

API: 073-06739

Operator: K3 OIL & GAS OPERATING

Inspection Date: 3/17/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06739 | Date: 3/17/2021

## Inspection Photos



**Photo 1.** Facing north at the beginning of the access road. The cattleguard remains and the fence has not been put back to original place.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06739 | Date: 3/17/2021

## Inspection Photos



**Photo 2.** Facing northeast toward the location. The perimeter of the location is fenced.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06739 | Date: 3/17/2021

## Inspection Photos



**Photo 3.** Center of the location facing north.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06739 | Date: 3/17/2021

## Inspection Photos



**Photo 4.** Center of the location facing west.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06739 | Date: 3/17/2021

## Inspection Photos



**Photo 5.** Center of the location facing south.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06739 | Date: 3/17/2021

## Inspection Photos



**Photo 7.** Center of the location facing east.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06739 | Date: 3/17/2021

## Inspection Photos



**Photo 7.** View of groundcover shows insufficient desirable vegetation establishment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06739 | Date: 3/17/2021