

Inspection Photos

Location Name: N Parachute EF G29 595 Pad

Location ID: #335573

Inspection Date: March 19, 2021



Photo #1 – Sign at entrance to pad.



Photo #2 – Overview of cuttings management area from northwest.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: N Parachute EF G29 595 Pad

Location ID: #335573

Inspection Date: March 19, 2021



Photo #3 – Cut slope west of cuttings management area.



Photo #4 – View of cuttings management area from east.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources