

Well Name: Helton MVRD Gas Unit #1 **API #** 05-067-05412
Document Number: 693902837
Inspector: Catherine Roy
Corrective Action: Russian thistle debris, up to 2-3 feet tall and wide observed within the project area and east of the project fill slope where it has blown off of the well pad.
Remove and properly dispose of weed debris by 3/31/2021. Manage weeds to prevent debris.

Correction Action Due: 3/31/2021
Action Completed: 3/10/2021
Action Taken: Removed and disposed of weed debris.

