

Inspection Photos

3/16/2021

Operator: CHEVRON USA INC - 16700

Location ID: 324350

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 324350



Photo 1: Photo taken from the north end of the Location, facing northeast. Photos 1-4 provide an overview of the production areas, interim areas, and the cuttings pit on the Location from northeast, east, southeast, south to southwest.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 324350



Photo 2: See comments under photo 1.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 324350



Photo 3: See comments under photo 1.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 324350



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 324350



Photo 5: Photo taken from the west end of the cuttings pit, facing north. Photo 5-7 provide an overview of the cuttings pit from north, northeast to east.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 324350



Photo 6: See comments under photo 5.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 324350



Photo 7: See comments under photo 5.

Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 324350



Photo 8: Photo of wellhead.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 324350



Photo 9: Photo of signage at the tank. Photo shows the emergency contact label on the sign is fading, and becoming difficult to read. Maintenance advised.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 324350



Photo 10: Photo shows signage at the cuttings pit.



Inspection Photos
Operator Name: CHEVRON USA INC - 16700
Location ID: 324350



Photo 11: Photo taken from containment berm around the separator equipment on the northeast end of the Location. Wildlife appear to be digging into the containment BMP; Ensure integrity of the containment BMP remains adequate.