

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #1 Location



Photo #2 Removed unused equipment

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #3 Removed unused equipment

Photo #4 Removed Trash

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #5 Removed Stained Soil/ Fixed Mechanical Conditions

Photo #6 Removed Stained Soil/ Fixed Mechanical Conditions

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #7 Removed Stained Soil/ Fixed Mechanical Conditions

Photo #8 Removed Stained Soil/ Fixed Mechanical Conditions

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #9 Removed Stained Soil/ Fixed Mechanical Conditions

Photo #10 Removed Stained Soil/ Fixed Mechanical Conditions

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Mar 23, 2021 at 8:32:33 AM
+40.3392, -104.4332
Weld
Colorado Oil & Gas Conservation Commission



Mar 23, 2021 at 8:33:55 AM
+40.3394, -104.4332
Weld
Colorado Oil & Gas Conservation Commission

Photo #11 Removed Trash

Photo #12 Removed Trash

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #13 Removed Stained Soil

Photo #14 Removed Stained Soil

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #15 Removed Stained Soil

Photo #16 LO/TO and marked

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #17 Removed Stained soil and oily waste

Photo #18 Removed Trash

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #19 Removed stained soil

Photo #20 Removed Stained soil

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #21 Removed Stained Soil/ Fixed Mechanical Conditions

Photo #22 Removed Stained Soil/ Fixed Mechanical Conditions

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #23 Removed Stained Soil

Photo #24 Removed Trash

Inspection Photos
Location Name: 70 Ranch 4-63-3 Pad
Location ID: 434077



Photo #25 Unmarked Riser