

Inspection Photos

Location Name: North Platte 24-34 Compressors Location

Facility ID: 447084



Photo #1 Location



Photo #2 Compressors Location

Inspection Photos

Location Name: North Platte 24-34 Compressors Location

Facility ID: 447084



Photo #3 Oily Skid/ Mechanical Conditions



Photo #4 Oily Skid/ Mechanical Conditions



Inspection Photos
Location Name: North Platte 24-34 Compressors Location
Facility ID: 447084




Photo #5 Oily Skid/ Mechanical Conditions

Photo #6 Oily Skid/ Mechanical Conditions

Inspection Photos
Location Name: North Platte 24-34 Compressors Location
Facility ID: 447084



Photo #7 Oily Skid/ Mechanical Conditions



Photo #8 Oily Skid/ Mechanical Conditions

Inspection Photos

Location Name: North Platte 24-34 Compressors Location

Facility ID: 447084



Photo #9 Oily Skid/ Mechanical Conditions



Photo #10 Oily Skid/ Mechanical Conditions



Inspection Photos

Location Name: North Platte 24-34 Compressors Location

Facility ID: 447084



Mar 23, 2021 at 9:54:54 AM

+40.3487, -104.4241

Weld

Colorado Oil & Gas Conservation Commission

Photo #11 Oily Skid/ Mechanical Conditions



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: North Platte 24-34 Compressors Location

Facility ID: 447084



Photo #12 Packing vent lines dripping into bucket



Photo #13 Packing vent lines dripping into bucket



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources