

Inspection Photos
Location Name: North Platte P-T-34 HZ Pad
Location ID: 429920



Photo #1 Well




Photo #2 New Placard

Inspection Photos
Location Name: North Platte P-T-34 HZ Pad
Location ID: 429920



Photo #3 Repaired Berm



Photo #4 Repaired Berm

Inspection Photos
Location Name: North Platte P-T-34 HZ Pad
Location ID: 429920



Photo #5 Repaired Berm



Photo #6 Removed Stained soil

Inspection Photos
Location Name: North Platte P-T-34 HZ Pad
Location ID: 429920



Photo #7 Not "LO/TO" riser



Photo #8 Not "LO/TO" or Marked on both risers