

Inspection Photos
Location Name: North Platte P-T-34 HZ
Location ID: 429920



Photo #1 Well



Photo #2 Mechanical Conditions replace or fix



Inspection Photos
Location Name: North Platte P-T-34 HZ
Location ID: 429920



Photo #3 Mechanical Conditions replace or fix



Photo #4 Mechanical Conditions replace or fix & Stained Soil

Inspection Photos
Location Name: North Platte P-T-34 HZ
Location ID: 429920



Photo #5 Mechanical Conditions replace or fix



Photo #6 Mechanical Conditions replace or fix

Inspection Photos
Location Name: North Platte P-T-34 HZ
Location ID: 429920



Photo #7 Mechanical Conditions replace or fix



Photo #8 Mechanical Conditions replace or fix & Stained Soil



Inspection Photos
Location Name: North Platte P-T-34 HZ
Location ID: 429920



Photo #9 Stained Soil



Photo #10 Mechanical Conditions replace or fix



Inspection Photos
Location Name: North Platte P-T-34 HZ
Location ID: 429920



Photo #11 Mechanical Conditions replace or fix



Photo #12 Oily Waste

Inspection Photos
Location Name: North Platte P-T-34 HZ
Location ID: 429920



Photo #13 Mechanical Conditions replace or fix



Photo #14 Stained Equipment



Inspection Photos
Location Name: North Platte P-T-34 HZ
Location ID: 429920



Photo #15 Trash



Photo #16 Trash

Inspection Photos
Location Name: North Platte P-T-34 HZ
Location ID: 429920




Photo #17 Trash



Photo #18 Mechanical Conditions replace or fix

Inspection Photos
Location Name: North Platte P-T-34 HZ
Location ID: 429920




Photo #19 Oily Waste/ Open netting



Photo #20 Oily Waste

