

Inspection Photos

Location Name: North Platte P-T-34HZ Compressor Location

Location ID: 429920



Photo #1 Compressor



Photo #2 Stained soil/ Oily Waste

Inspection Photos

Location Name: North Platte P-T-34HZ Compressor Location

Location ID: 429920



Photo #3 Mechanical Conditions/ Oily Waste



Photo #4 Mechanical Conditions/ Oily Waste