

Inspection Photos
Operator: Simcoe
Facility: 067-08680
Date: 3/16/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area facing westward. Dense kochia debris observed.



Photo 3. View of more kochia debris on the well pad.



Photo 4. View of reference area comprised of open grass field, largely dormant at this time.