

Inspection Photos

Loc#334563

Operator: Caerus

Insp#: 692403241

Insp Date: 3/17/21



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry.

March 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Parker Ranch Loc#334563



Photo#2:
West leg of site.



Photo#3:
Chuff pile at West end of site.

March 17, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Parker Ranch Loc#334563