



Whiting Oil & Gas Corporation

HORSETAIL 30E PAD CORRECTIVE ACTION INSPECTION PHOTOS

Location ID: 445049

Sec 30 T10N R57W

1-25-21



Horsetail 30E-3103 Wellhead Sign Installed



Horsetail 30E-1935 Wellhead Sign Installed



Whiting Oil & Gas Corporation

HORSETAIL 30E PAD CORRECTIVE ACTION INSPECTION PHOTOS

Location ID: 445049

Sec 30 T10N R57W

3-24-21



Horsetail 30E-1934 Wellhead Sign Installed