

Inspection Photos
Location Name: Robert G Berge #2
Spill ID 476918 (CL)/ Remediation Project No. 15743



Photo 1 – Open spill excavation adjacent to Brantner Irrigation ditch. A portion of the irrigation ditch wall has collapsed into open excavation; remaining portion of the ditch wall next to excavation appears unstable.

Photo 2 – Collapsed wall of Brantner Irrigation ditch into open excavation.