




40.12186, -108.18212, 6037.6ft, 55°
03/23/2021 03:01:20 PM





40.12209, -108.18173, 6019.7ft, 68°
03/23/2021 03:02:17 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well with gas leak.

Ant Hill 30-31
API: 05-103-09909



40.12207, -108.18167, 6017.1ft, 333°
03/23/2021 03:03:30 PM



40.12183, -108.18205, 6036.4ft, 23°
03/23/2021 03:01:34 PM



40.12196, -108.1815, 6030.3ft, 188°
03/23/2021 03:04:47 PM



40.12188, -108.18145, 6016.6ft, 218°
03/23/2021 03:04:15 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Hole in corner of tank secondary containment.

Ant Hill 30-31
API: 05-103-09909



40.12211, -108.18168, 6013.2ft, 75°
03/23/2021 03:02:25 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. Chemical label.

Ant Hill 30-31
API: 05-103-09909