

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2021

Submitted Date:

03/27/2021

Document Number:

695104164**FIELD INSPECTION FORM**Loc ID 333672 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271048	WELL	PR	08/01/2004	GW	071-07972	MAGIC 14-4	PR
273656	WELL	PR	12/29/2004	GW	071-08199	MAGIC 14-4 TR	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

Phone 3: PILE OF E&P WASTE APPEARS TO BE FRAC SAND AND PERF DUST
BAILED FROM WELL BORE NEXT TO WELLHEAD.

Corrective Action:

COMPLY WITH RULE 905.f. AND 1002.F.(2)F

Date: 04/07/2021

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead

2

Comment:

BOTH ARE PLUMBED TO SURFACE

Corrective Action:

Date:

Type: Gas Meter Run

2

Comment:

BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN
THE LAST YEAR.

Corrective Action:

Date:

Venting:

Yes/No

NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 271048 Type: WELL API Number: 071-07972 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Facility ID: 273656 Type: WELL API Number: 071-08199 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	278531	1175488	
	278935	1445924	