

Inspection Photos

3/25/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335171

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335171



Photo 1: Photo taken from the northwest end of the Location, facing north. Photo shows that control measures to stabilize/protect the cut/fill slopes of the Location are missing or insufficient

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335171



Photo 2: Photo taken from the northwest end of the Location, facing northwest. Photo shows that control measures to stabilize/protect the cut/fill slopes of the Location are missing or insufficient

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335171



Photo 3: Photo taken from the northwest end of the Location, facing northeast. Photo shows that control measures to stabilize/protect the cut/fill slopes of the Location are missing or insufficient

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335171



Photo 4: Photo taken from the north end of the Location, facing north. Photo shows that control measures to stabilize/protect the cut/fill slopes of the Location are missing or insufficient

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335171



Photo 5: Photo taken from the northeast end of the Location, facing west. Photo shows that control measures to stabilize/protect the cut/fill slopes of the Location are missing or insufficient

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 335171



Photo 6: Photo taken from the north end of the Location, facing north. Photo shows that control measures to stabilize/protect the cut/fill slopes of the Location are missing or insufficient