

Caerus Piceance LLC
B16E
Location # 334951

Mar 29, 2021 at 2:03:11 PM
39.450149,-107.670945 ±4.75m
COGCC



location

Mar 29, 2021 at 2:06:19 PM
39.450328,-107.670452 ±4.75m
COGCC



location

Caerus Piceance LLC
B16E
Location # 334951

Mar 29, 2021 at 2:05:40 PM
39.450242,-107.670523 ±4.74m
COGCC



location

Mar 29, 2021 at 2:06:31 PM
39.450328,-107.670452 ±4.75m
COGCC



location

Caerus Piceance LLC
B16E
Location # 334951



Signage falling off

Caerus Piceance LLC
B16E
Location # 334951



Unmarked anchor



Lack of stabilization/compaction

Caerus Piceance LLC
B16E
Location # 334951



Lack of stabilization/compaction

Caerus Piceance LLC
B16E
Location # 334951

Mar 29, 2021 at 2:02:19 PM
39.450254,-107.671015 ±4.78m
COGCC



Debris