



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Rangely South 9-4-1-102 API: 05-103-09026
Inspection: 701500140



39.99261, -108.83954, 5956.1ft, 21°
03/30/2021 04:33:11 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Meter building.

Rangely South 9-4-1-102 API: 05-103-09026
Inspection: 701500140



39.99245, -108.83941, 5973.5ft, 54°
03/30/2021 04:33:35 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Separator & tank.

Rangely South 9-4-1-102 API: 05-103-09026
Inspection: 701500140



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Well sign frame.

Rangely South 9-4-1-102 API: 05-103-09026
Inspection: 701500140