


**Inspection Photos**  
**Location Name: Hiawatha Unit 2**  
**Location ID: 312835**



**Photo 1. Overview of location taken facing southwest.**



**Photo 2. No bradenhead access apparent.**

