

Inspection Photos

API: 071-07409

Operator: OGRIS OPERATING LLC

Inspection Date: 4/1/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07409 | Date: 4/1/2021

Inspection Photos



Photo 1. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07409 | Date: 4/1/2021

Inspection Photos



Photo 2. The wall panel near the meter shed has fallen over.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07409 | Date: 4/1/2021

Inspection Photos



Photo 3. The wall panel is leaning on the pipe riser. Pipe riser are not LOTO.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07409 | Date: 4/1/2021