

Inspection Photos

API: 071-06124

Operator: OGRIS OPERATING LLC

Inspection Date: 4/1/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06124 | Date: 4/1/2021

Inspection Photos



Photo 1. Facing southwest along the main road. Vehicles are driving around where water is accumulating in the road causing widening of the road. This area needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06124 | Date: 4/1/2021

Inspection Photos



Photo 2. There is vehicle rutting along the main road traveling southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06124 | Date: 4/1/2021

Inspection Photos



Photo 3. Facing southwest along the main road near the location. Vehicles have caused widening of the road and causing damage outside of road boundary. Vehicles shall not travel outside of access road boundary per rule 1002.e(4).



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06124 | Date: 4/1/2021

Inspection Photos



Photo 4. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06124 | Date: 4/1/2021

Inspection Photos



Photo 5. There is still oil inside the engine skid that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06124 | Date: 4/1/2021