

Inspection Photos

API: 071-06219

Operator: OGRIS OPERATING LLC

Inspection Date: 4/1/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06219 | Date: 4/1/2021

Inspection Photos



Photo 1. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06219 | Date: 4/1/2021

Inspection Photos



Photo 2. Well is temporarily abandoned. No LOTO on pipe risers.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06219 | Date: 4/1/2021

Inspection Photos



Photo 3. Exposed electric line near the wellhead.

