

# Inspection Photos

API: 071-09820

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/5/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09820 | Date: 4/5/2021

## Inspection Photos



**Photo 1.** Facing southwest toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09820 | Date: 4/5/2021



## Inspection Photos



**Photo 2.** Panels of the sound wall are laying on the ground.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09820 | Date: 4/5/2021

## Inspection Photos



**Photo 3.** There is oil in the engine skid. Engine parts laying near the engine.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09820 | Date: 4/5/2021