

**CM Production Bond Claim: Task 3.1 - Mechanical Integrity Test - 324626, 057-06069  
Margaret Spaulding 7**

Prepared 3/2/2021

**FIELD NAME** Lone Pine  
**FIELD NUMBER** 51375

**LOCATION**  
Basin North Park  
Location-Section-Township-Range NENE 33 9N81W  
Location-Lat/Long 40.714271/-106.493056  
Elevation 8,426 KB  
8,409 GR

**COGCC Document No.**

Status: SI 8/1/2014  
**Notes:**  
Spud 5/9/1973  
Last MIT Failed  
Pump jack No  
Rods and pump ?  
Tubing size ?  
Tubing depth ?

