


CM Production Bond Claim: Task 3.1 - Mechanical Integrity Test - 324632, 057-06095
Margaret Spaulding 12-A

Prepared	3/2/2021		
FIELD NAME	Lone Pine		
FIELD NUMBER	51375		
<u>LOCATION</u>			
Basin	North Park		
Location-Section-Township-Range	SWNE 33 9N81W 6 PM		
Location-Lat/Long	40.712309/-106.49822		
Elevation	8,289	KB	
	8,280	GR	



COGCC Document No.	
Status	SI 3/25/2013
<u>Notes:</u>	
Spud	2/23/1974
Last MIT	NA
Pump jack	Yes, Jet pump
Rods and pump	?
Tubing size	?
Tubing depth	?
Need to pull rods & pump	

