

Inspection Photos

4/6/2021

Operator: OXY USA INC - 66561

Location ID: 312499

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: OXY USA INC - 66561
Location ID: 312499



Photo 1: Photo taken from the south end of the Location, facing north. Pursuant with 1004 Rules, final reclamation activities were required to be completed by 2012

Inspection Photos
Operator Name: OXY USA INC - 66561
Location ID: 312499



Photo 2: Photo shows large areas of the Location remain bare and graveled.

Inspection Photos
Operator Name: OXY USA INC - 66561
Location ID: 312499



Photo 3: Photo shows large areas of the Location remain bare and graveled.

Inspection Photos
Operator Name: OXY USA INC - 66561
Location ID: 312499



Photo 4: Photo taken from the north end of the Location, facing south. Photo shows large areas of the Location remain bare and graveled. Compaction concerns exist. Unable to find evidence that final reclamation activities have been completed in accordance with 1004 Rules.

Inspection Photos
Operator Name: OXY USA INC - 66561
Location ID: 312499



Photo 5: Photo shows large areas of the Location remain bare and graveled. Photo shows example of a compaction test pit performed on the Location; compaction concerns evident at surface of the Location; unable to easily penetrate soil surface.

Inspection Photos
Operator Name: OXY USA INC - 66561
Location ID: 312499



Photo 6: Photo taken from the adjacent reference areas. Photo shows comparison of soils on the reference to that on the Location; Reclamation Specialist was able to easily penetrate to top foot of soil on the reference area.