

Inspection Photos

4/6/2021

Operator: LARAMIE ENERGY LLC #10433

Location ID: 312531

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312531



Photo 1: Photo taken from the location facing north. Photos 1-4 provide an overview of the Location from north, east, south to west. Photos show that the Location remains bare and exposed soil; desirable perennial vegetative germination not observed over majority of the Location; no control measures implanted to stabilize the seeded soils.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312531



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312531



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312531



Photo 4: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312531



Photo 5: Close up photo of soil surface of the Location; Location remains bare and exposed soil; desirable perennial vegetative germination not observed over majority of the Location; no control measures implanted to stabilize the seeded soils.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312531



Photo 6: Photo shows surface equipment remaining on the Location; equipment requires removal pursuant with Rule 1004.a

Inspection Photos
Operator Name: LARAMIE ENERGY LLC #10433
Location ID: 312531



Photo 7: Photo shows straw wattle BMPs have not been maintained in proper functioning condition, is now considered debris and requires removal.

