

Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744



Photo 1 – Wellhead Spill



Photo 2 – Wellhead Spill



Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744




Photo 3 – Wellhead Spill looking West



Photo 4 – Wellhead Spill

Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744



Photo 5 – Wellhead Spill looking West



Photo 6 – Wellhead Spill

Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744



Photo 7 – Wellhead Spill



Photo 8 – Wellhead Spill

Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744



Photo 9 – Wellhead Spill



Photo 10 – Wellhead Spill



Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744



Photo 11 – Wellhead Spill



Photo 12 – Wellhead Spill



Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744



Photo 13 – Wellhead Spill



Photo 14 – Wellhead Spill

Inspection Photos
Location Name: Staudinger 1-31H
Location ID: 424744




Photo 15 – Wellhead Spill



Photo 16 – Wellhead Spill

