

Inspection Photos

Loc#311595

Operator: Mustang

Insp#: 692403268

Insp Date: 4/5/21





Photo#1:
Overview of Location.

April 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos: Mustang Savage Loc#311595



Photo#2:
Debris along fence line.



Photo#3:
Debris along fence line.

April 5, 2021



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp Photos: Mustang Savage Loc#311595