

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MAHAFFEY-66S95W /25SESW

Location ID: 383332



Photo #3433 from entrance to location.



Photo #3434 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MAHAFFEY-66S95W /25SESW

Location ID: 383332



**Photo #3435 Multiple wellheads signs weathered and not legible.**



**Photo #3436 Location lacks stabilization.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MAHAFFEY-66S95W /25SESW

Location ID: 383332



**Photo #3437 No form of tracking control at entrance to location**



**Photo #3438 Access road lacks stabilization**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MAHAFFEY-66S95W /25SESW

Location ID: 383332



**Photo #3439 Access road lacks stabilization**



**Photo #3440 No public access.**