

# Inspection Photos

4/6/2021

Operator: LARAMIE ENERGY LLC #10433

Location ID: 334537

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 334537



Photo 1: Photo of sign at Location entrance.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 334537



**Photo 2:** Photo taken from east end of the Location, facing south. Photos 2-5 provide an overview of the Location from south, southwest, northwest to north.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 334537



**Photo 3:** See comments under photo 2.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 334537



**Photo 4:** See comments under photo 2.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 334537



**Photo 5:** See comments under photo 2.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 334537



**Photo 6:** Photo shows soil stockpile on the northeast end of the Location.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 334537



**Photo 7:** Photo taken from the northeaster area of the Location, facing west. Photo shows areas used for “land treatment”. Doc #400416420 submitted 05/10/2013 indicates that land treatment in the area on the north side of the pad had been successful. Photo shows land treatment areas remain on the Location; areas require reclamation in accordance with 1003 Rules.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 334537



**Photo 8:** Photo taken from the east end of the Location, facing north. See comments under photo 7.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC #10433  
Location ID: 334537



**Photo 9:** Photo taken from the west end of the Location, facing west. Photo shows areas associated with Rem. Proj. #5132.