

**Inspection Photos**  
**Location Name: Maudlin Gulch Unit 2**  
**Location ID: 332715**



**Photo 1. Overview of location taken facing west.**



**Photo 2. Stained soil at wellhead.**

