

Final Reclamation Inspection

April 7, 2021

Operator: BATES* JAMES EDWARD - 6575

API #: 05-005-06064

Inspection Document #: 697502761

Arapahoe County, CO

SWSW Section 14 T4S R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PRICE #1
API #: 05-005-06064



Photo 1. Photo taken from the tank battery, facing North. Photo illustrates topsoil has been hauled in and water bars installed but the area has not been seeded and straw mulched.



Inspection Photos
Location Name: PRICE #1
API #: 05-005-06064



Photo 2. Photo taken from the tank battery, facing South. See comments under Photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502761

Inspection Photos
Location Name: PRICE #1
API #: 05-005-06064



Photo 3. Photo taken from the tank battery, facing West. See comments under Photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697502761

Inspection Photos
Location Name: PRICE #1
API #: 05-005-06064



Photo 4. Photo taken from the tank battery, facing Southwest. See comments under Photo 1.



Inspection Photos
Location Name: PRICE #1
API #: 05-005-06064



Photo 5. Tank battery reference photo taken 1/8/2020 northwest of the tank battery, facing West. Photo illustrates blue grama as the dominant vegetative cover.

